

Read Me

System Software 9.1.8 Patch 1 RS35x, RS123

Deutsch Die folgenden Fehler sind behoben worden:

1.1 DSL - Unnötiger Verbindungsversuch

(ID 18444)

Auch wenn keine DSL-Leitung angeschlossen war, führte das Gerät wiederholt Synchronisierungsversuche durch. Dadurch konnte es dazu kommen, dass das Gerät nicht in allen Fällen wie erwartet reagierte.

1.2 UMTS - Verbindungsverlust

(ID 18561)

Es konnte dazu kommen, dass ein Gerät mit einem internen UMTS-Modem nach einiger Zeit die Verbindung zum Mobilnetz verlor. Durch Zurücksetzen konnte das Modem wieder funktionstüchtig gemacht werden.

English The following errors have been corrected:

1.1 DSL - Unnecessary connection attempt

(ID 18444)

Even if no DSL connection was available, the device made repeated synchronization attempts. This could have the effect that the device did not respond as expected under all circumstances.

1.2 UMTS - Connection lost

(ID 18561)

It could happen that a device with an internal UMTS modem lost connection to the mobile network after some time. Resetting the modem re-enabled the ability to connect.